

C WOOD & SON LUTON LTD


> Case Study



The Job

C Wood & Son Luton Ltd were contracted to carry out this HMO project after a previous contractor failed to deliver.

We had to remove 70% of the previous contractors work, before we could begin, as it was not up to standards. There was dry rot found to 30% of the property that needed to be treated. We had to take this property back to a shell and start with a blank canvas.



The client was so pleased with the quality of our work and the capabilities of our staff, The client already wants to contract us to carry out their next project.



