

C WOOD & SON LUTON LTD

> Case Study



Courtyard by Marriott, Luton Airport

The Job

C Wood and Son were employed by the Courtyard by Marriott Hotel at Luton Airport.to carry out a small project in one of their stairwells.

Hotels are still able to operate during the Covid-19 Lockdown in England but only for key workers, those who have to travel for



work, education and/or other legal purposes. However, the hotel were keen to get this small project completed whilst they still have guests.

For this project we:

- Cleared the materials/items from the area under the stairs and set aside.
- Had to remove the existing stud wall.

 Installed a new stud wall with a 1 hour fire rating.
 - Install 1hr fire door and frame for access.
 - Decorated the wall.
 - Decorated the door and frame.

This project was completed in 3 days.

Clients were happy with the finished result and the short time scale in which it was completed. Great effort from our guys.















