



C WOOD & SON  
LUTON LTD

# Case Study



New Front Wall  
Luton

# The Job

C Wood and Son were employed to knock down the remains of a damaged front garden wall at a residential property in Luton and re-build a new one.

For this project we:

- Knocked down the remaining wall.
- Cleared all rubble away.
- Built a new 4" wall with 3No 9" piers to match the existing.

This project was completed in 4 days, just in time for the Easter weekend.









