



C WOOD & SON
LUTON LTD

Case Study

A photograph of a green front door with a white surround. The door has two vertical glass panels with decorative leaded glass patterns, a brass handle, a brass knocker, and a brass letterbox. The door is set in a white frame against a brick wall. A green plant is visible on the right side of the door.

**Roof Repairs, Fascia & Soffits
Aston End, Stevenage**

The Job

C Wood and Son were employed to carry out main roof repairs to a property in Aston End, Stevenage, along with the removal of asbestos soffits,



For this project we carried out the following Garage:

- Removed the vegetation and disposed of.
- Removed the asbestos soffits under controlled conditions.
- Disposed of at a licensed waste transfer station and supplied a consignment note for proof of safe disposal.
- Installed new UPVC, fascia, soffit and gutters.

Main House:

- Removed the asbestos soffit to the front and left gable under controlled conditions.
- Disposed of at a licensed waste transfer station and supplied a consignment note for the roof of safe disposal.
- Installed new UPVC fascia, soffit and gutters to the front and side gable.
- Re-pointed the chimney.
- Erected tower scaffolds and took off first 3No rows of tiles and set aside for re-use.
- Removed first section of felt and battens and installed new with eaves tray.
- Installed new roof tiles.
- Installed a new composite front door, build new surround to match the existing and decorate with undercoat and gloss.
- Install lead to canopy.

This project was completed in 2 weeks.







