



C WOOD & SON
LUTON LTD

Case Study



Asbestos Removal & Building Renovation
Wheathampstead

The Job

C Wood & Son Luton Ltd removed asbestos sheeting from the roof and sides of an old barn to leave the steel frames.

The team then dug out the floor and footing and laid out the concrete. We then built dwarf walls to the perimeter and installed stud work ready to form a coffee shop area, first floor offices and a store at the rear.

We installed the electrics, plumbing and carpentry as well as fitting shiplap onto the outside of the barn; finishing off with installing windows.



BEFORE



AFTER

