



C WOOD & SON
LUTON LTD

Case Study



**Structural Works
Kimpton**

The Job

C. Wood & Son were employed by a family in Kimpton to undertake the structural works within their property.



For this project we:

- Removed the conservatory and disposed
- Took up old screed to conservatory floor
- Removed the flooring to the kitchen/dining and hall
- Stripped out the kitchen and pantry
- Taken down the kitchen/dining ceiling
- Supported the ceiling joists with acro's
- Removed the walls as per SE drawings
- Installed steels as per SE drawings
- Installed steel to support the chimney breast
- Cut out a new doorway to the study
- Cut out the doorway for the cloak room and installed lintel
- Removed the French doors and bricked up to form a window opening
- Cut out a new opening and installed lintel to the en suite.

This project was completed in 2 weeks and our clients were delighted with the end result, as are we.

Great workmanship as always from our tradesmen.















