

C WOOD & SON LUTON LTD

> Case Study



The Job

C. Wood & Son were employed by a family in Luton to undertake the renovation of their garden.



- Removed and disposed of old gate and fencing
 - Broke up old concrete base and dug out existing flowerbed and disposed of
 - Repaired broken drain pipe and laid MOT ready for concrete base
 - Installed wooden sleepers to make raised flower beds and laid topsoil within them.
 - Installed new fence posts and fence panels
 - Decorated new fencing
 - Installed concrete base
 - Installed new iron security gate

This project was completed in 2 weeks and our clients were delighted with the end result, as are we.

Great workmanship as always from our tradesmen.









































