



C WOOD & SON  
LUTON LTD

# Case Study



**Tank Removal & Alterations  
Luton**

# The Job

C. Wood & Son were employed by a family in Luton to undertake the removal of a steel water tank at their property.



For this project we:

- Erected a tower scaffold
- Cut up and disposed of the steel water tank
- Built up new brickwork to form a parapet wall
- Installed new joists and ply decking
- Installed felt roof and flashings
- Toothed out and bricked up the existing door to the outside cupboard
- Removed the internal wall
- Installed floor joists and chipboard flooring

This project was completed in 4 weeks and our clients were delighted with the end result, as are we.

Great workmanship as always from our tradesmen.



















