



C WOOD & SON
LUTON LTD

Case Study



New Kitchen
Luton

The Job

C. Wood & Son were employed by a family in Luton to undertake the installation of a new kitchen unit at their property.



For this project we:

- Taken down ceiling and disposed of
- Supplied and installed plasterboard and skim
- Removed the sink and taps and disposed of
- Removed the hob and set aside for reuse
- Removed worktops and bottom row of wall tiles and disposed of
- Supplied and installed new worktops
- Supplied and installed Alusplash back around worktop
- Refitted hob, new sink and taps
- Supplied and installed new LED light fitting to kitchen ceiling
- Supplied and installed outside tap
- Supplied and installed outside double socket
- Cleared site upon completion

This project was completed within 2 weeks and the clients were delighted with the end result, as are we.

Great workmanship as always from our tradesmen.





