



C WOOD & SON
LUTON LTD

Case Study

Installation of Rafter Ends
Luton

The Job

C. Wood & Son were employed by St Francis Church in Luton, to undertake the installation of 3 new rafter ends.

For this project we:

- Supplied welfare and fencing
- Replaced the 3No Oak rafter ends to match original specification
- Installed oak capping to rafters
- Decorated with Osmo oil
- Cleared site upon completion

This project was completed in 4 weeks and the clients were delighted with the end result.

A great job all round from the team.













