



C WOOD & SON
LUTON LTD

Case Study

**Church Extension
Ickleford**

The Job

C. Wood & Son were employed by to undertake a huge extension project, the installation of a new kitchen layout and general repair works to a church in Hertfordshire.



For this project we:

- Underpinned buttresses and laid concrete slabbing.
- Completed the brick, block and stone work
- Installed drainage and steelwork
- Laid flooring
- Plastered the entire extension area
- Installed new kitchen, windows and main door
- Installed stainless steel roof, roof windows and stone copings
- Made and installed oak door and frame to connect the church to the extension
- Installed electrics and plumbing
- Created a pathway outside and finished with tarmac
- Cleared site upon completion

This project was completed in 12 months due to the complications and restrictions the pandemic had.

We stuck through the difficulties, the delayed material deliveries and completed a job the clients were delighted with.

Great workmanship as always from our tradesmen and incredible effort from all those involved..















