




C WOOD & SON
LUTON LTD

Case Study



Wall Demolition & Rebuild
Great Gransden, Sandy

The Job

C. Wood & Son were employed by another company to carry out a heritage wall project in Gransden, Sandy.

For this project we:

- Removed pier caps and set them aside
- Took down section to the front wall, 2No piers and railings
- Took down solid sloped walls
- Cleaned the bricks for reuse
- Dug footings
- Rebuilt the 9" walls and 2No piers in Flemish bond, using Cambridge Gault handmade bricks and Lime Mortar to match the existing
- Refitted the pier caps we set aside at the beginning
- Cleared site on completion

This project was tricky from the start due to needing traffic management and working around the poor weather conditions earlier this year, but the team did a fantastic job.











