



C WOOD & SON
LUTON LTD

Case Study

**New Shower Tray
Hilton Garden Inn, Luton**

The Job

C. Wood & Son were employed by the Hilton Garden Inn Hotel, to carry out a small bathroom refurb to one of their rooms in their Luton hotel. .



For this project we:

- Removed the shower screen and set aside for reuse
- Carefully removed the bottom row of tiles and set aside for reuse
- Removed the damaged shower tray and disposed of
- Installed new shower tray
- Refitted bottom row of tiles we set aside at the beginning
- Refitted the shower screen we set aside at the beginning
- Cleared site on completion

This project was completed in 2 days.

The client was thrilled with the finished result. A great job all round from the team!



