



C WOOD & SON
LUTON LTD

Case Study



Pathway
Luton, Bedfordshire

The Job

C. Wood & Son were employed by Maidenhall Primary School, Luton, to investigate an issue they had with o



For this project we:

- Ensured no school children were around for their own safety and that the area we were working in was safe and would cause no disturbances.
- Cut out the damaged path to assess underneath.
- Made good underneath so it was nice and level.
- Tarmacked the path where we dug out.

We have since quoted to have the tree removed to prevent the same issue further down the line and to avoid accidents within the school.

The school are a new client of ours and we've been more than happy helping them with their maintenance of the building and on-going projects!

Great work guys.



