


C WOOD & SON LUTON LTD

> Case Study



The Job

C. Wood & Son were employed by local trustees to carry out roofing repairs and maintenance to a Grade II listed building in Northchurch, Hertfordshire.



- Arranged parking and scaffolding permits, along with traffic management for a two week period, to the front elevation
- Erected scaffolding to the front elevation in guideline with our permit to allow safe working and minimal disruption to the general public
- Cleaned all gutters, downpipes, gullies and overhaul
- Cleared the moss from all roof elevations
- Took off the ridges and re bed them with lime mortar
- Replaced 50No missing and/or broken tiles
- Re-bed the missing tiles to fillet around chimneys with lime mortar
- Cleared scaffolding, traffic management and materials from site on completion

This project was a a tricky one due to managing this around poor weather conditions, sticking into the timeframe for permits and ensuring both workers and members of the public were safe at all times.

The finished result is a happy, semi-restored Grade II listed building.

Great job to all those involved!

































